



Legend

	BEN		BOTTOM BANK
	BOLLARD		BENCH
	BUSH		BUILDING
	EX STUD		BUILDING OPEN
	FIRE HYDRANT		BASE WALL
	GRS STATION		CHANNEL
	GILLY		CONCRETE
	HOLE		CHANGE SURFACE
	INSPECTION CHAMBER		CANOPY
	INVERT LEVEL		DROP KERB
	JUNCTION BOX		EDGE GROWTH
	LAMP POLE		FENCE
	MAN HOLE		FENCE 1.8M HT.
	MAN HOLE CIRCULAR		FENCE 1.4M HT.
	POST		FOOTPATH
	ROAD SIGN		PALISADE FENCE
	SPOT LEVEL		FENCE 2.0M HT.
	STAY		GATE
	STUMP		HAND RAIL
	STOP VALVE		INSPECTION CHAMBER
	TREE		KERB
	TRAFFIC LIGHT		TOP BANK
	WATER LEVEL		TOP WALL
			VISI RAIL

Station	Bearing	Wearing	Level
CA1	247323.874	217352.654	136.393
CA2	247322.725	217357.659	136.159
CA3	247322.725	217357.659	136.159
CA4	247322.725	217357.659	136.159
CA5	247321.012	217357.910	136.180

REV	DATE	AMENDMENT	BY	CHK'D

CLIENT
 CWM Environmental
 Nantycaws Landfill Site
 Llanidderog Road
 Nantycaws
 Carmarthen

DRAWING TITLE & SCHEME
 Nantycaws Landfill Site
 Update Survey September 2022
 Landfill area

Drawing Number CWM_09-2022	Drawn By : DB
Date : 01/2023	Scale : 1 : 1500 (A0)
Checked : 0000	